

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,443,241 B1
DATED : September 3, 2002
INVENTOR(S) : Juhasz et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 8,

Line 18, after "a low" insert -- second --.

Line 67, after "ing:" insert the following:


-- a lower second drive shaft coupled to the top drive output shaft and comprising an adjustable segment that is selectively adjustable to adjust the length of the second drive shaft;

means for applying a force to the second shaft to cause the length of the adjustable segment to be shortened; and --

This certificate supersedes Certificate of Correction issued May 18, 2004.

Signed and Sealed this

Twenty-sixth Day of July, 2005



Jon W. Dudas

JON W. DUDAS
Director of the United States Patent and Trademark Office